to MP Volume 46 Subject Index

This is an alphabetical listing of primary topics included in Volume 46 of MP. Subject classifications are followed by issue number, then page number. An alphabetized list of authors appears on p. 87.

Aboveground storage tank	MMO-Coated Titanium Anodes for	Brass
MMO-Coated Titanium Anodes for	Cathodic Protection—Part 2 6-24	Case Histories: Stress Corrosion Cracking
Cathodic Protection—Part 2 6-24		of Various Alloys-Part 1 8-77
	Anode, coating	
Acidity	Cathodic Protection of a Shiplock Trash	Brass, admiralty
Phlogiston and Modern Corrosion Junk	Rack at a Hydropower Station 11-30	Creep Failure of Admiralty Brass Tubes in
Science 3-34	MMO-Coated Titanium Anodes for	an After-Cooler 1-52
	Cathodic Protection—Part 1 5-26	m.11
Acrylic resin	MMO-Coated Titanium Anodes for	Bridge
Tanninsulfonic Acid-Doped Polyaniline for	Cathodic Protection—Part 2 6-24	Anode Selection for Protection of
Protection of Cold-Rolled Steel 2-38		Reinforced Concrete Structures 1-26
A 4-0451-1-1	Anode, deep bed	Braminated anam.
Additive, non-skid	Check Solar Weather Before Performing	Brominated epoxy
Painting at Night in the Gulf of Mexico 2-31	Pipeline CP Evaluation 6-30	Properties of a New High-Tg FBE Coating
Admiralty brass	MMO-Coated Titanium Anodes for	for High-Temperature Service 4-36
Creep Failure of Admiralty Brass Tubes in	Cathodic Protection—Part 2 6-24	Bronze
an After-Cooler1-52		Corrosion of Old Whaling Station
all Alter-Cooler	Anode, mixed metal oxide	Processing Equipment in Antarctica 4-57
After-cooler	Anode Selection for Protection of	Frocessing Equipment in Antarctica 4-37
Creep Failure of Admiralty Brass Tubes in	Reinforced Concrete Structures 1-26	Building, steel-framed
an After-Cooler 1-52	MMO-Coated Titanium Anodes for	Anode Selection for Protection of
	Cathodic Protection—Part 1 5-26	Reinforced Concrete Structures 1-27
Agitation	MMO-Coated Titanium Anodes for	Treminorcea Concrete Citactares 1-27
Agitator Corrosion in Wet Phosphoric Acid	Cathodic Protection—Part 2 6-24	Carbon fiber
Production2-51		Anode Selection for Protection of
	Anode, probe	Reinforced Concrete Structures 1-27
Agitator, reactor	Anode Selection for Protection of	
Agitator Corrosion in Wet Phosphoric Acid	Reinforced Concrete Structures 1-27	Carbon steel
Production 2-50		A New Method for Pipeline Integrity
	Anode, ribbon	Management 1-42
Alloy	Anode Selection for Protection of	•
Corrosion of UNS N06625 Nozzles in a	Reinforced Concrete Structures 1-27	Cast iron
Biomass Fluidized Bed Boiler 9-74		Longevity of a Graphitized Cast Iron Water
	Anode, silicon iron	Main 5-30
Alloy, Inconel	Anode Selection for Protection of	
Case Histories: Stress Corrosion Cracking	Reinforced Concrete Structures 1-26	Cathodic disbondment
of Various Alloys—Part 2 9-71	Amelianica	Properties of a New High-Tg FBE Coating
	Appliqués	for High-Temperature Service 4-36
Alloy, steel	Appliqués for Corrosion Protection in a	0.1.11
Case Histories: Stress Corrosion Cracking	Tropical Environment 6-38	Cathodic protection
of Various Alloys—Part 2 9-69	Asphaltic coating	Anode Selection for Protection of
Aluminum	Analysis of Ductile Iron Corrosion Data	Reinforced Concrete Structures 1-26
		Cathodic Protection of a Shiplock Trash
Case Histories: Stress Corrosion Cracking	from Operating Mains 2-22	Rack at a Hydropower Station 11-30
of Various Alloys—Part 2 9-72	Austenitic stainless steel	Check Solar Weather Before Performing
Anaerobic slime	Chloride Stress Corrosion Cracking of UNS	Pipeline CP Evaluation 6-30
Lining Prevents Biogenic Sulfide Corrosion	S20910 Stainless Steel 1-58	Correcting CIPS for Stray and Telluric
In Wastewater Systems 5-36	OLOUTO Otaliness Oteel	Current Interference 10-24
III Wastewater Systems 5-30	Bacteria, sulfate-reducing	Corrosion Mitigation of USS Monitor
Annealing	Detecting and Monitoring Bacteria in	Artifacts 10-56
Sigma Phase Formation of Type 310	Seawater Injection Systems 11-52	Galvanic Corrosion Study of Tin-Silver
Stainless Steel in a Lime Kiln Burner	Effect of Biogenic Sulfide on Corrosion of	Solder and Copper 6-58
Nozzle	Mild Steel 6-48	Internal Stray Current Interference from an
1402216 5-37		
Anode	SRB-Assisted MIC of Fire Sprinkler	External Current Source 8-40
Anode Selection for Protection of	Piping 2-46	I Told You So
Reinforced Concrete Structures 1-26	Biogenic sulfide	Low-Alloy Steels for Reinforcing Rods in
Cathodic Protection of a Shiplock Trash	Effect of Biogenic Sulfide on Corrosion of	Concrete 5-50
	Mild Steel 6-48	Mitigation Techniques for AC-DC Cathodic
Rack at a Hydropower Station 11-30		Decoupling 12-30
Galvanic Corrosion Study of Tin-Silver	Lining Prevents Biogenic Sulfide Corrosion	MMO-Coated Titanium Anodes for Cathodi
Solder and Copper 6-58	in Wastewater Systems 5-36	Protection—Part 1 5-20
MMO-Coated Titanium Anodes for	Understanding Biogenic Sulfide	MMO-Coated Titanium Anodes for Cathodi
Cathodic Protection—Part 1 5-26	Corrosion 11-36	Protection—Part 2 6-24

to MP Volume 46 Subject Index

This is an alphabetical listing of primary topics included in Volume 46 of MP. Subject classifications are followed by issue number, then page number. An alphabetized list of authors appears on p. 87.

Aboveground storage tank	MMO-Coated Titanium Anodes for	Brass
MMO-Coated Titanium Anodes for	Cathodic Protection—Part 2 6-24	Case Histories: Stress Corrosion Cracking
Cathodic Protection—Part 2 6-24		of Various Alloys-Part 1 8-77
	Anode, coating	
Acidity	Cathodic Protection of a Shiplock Trash	Brass, admiralty
Phlogiston and Modern Corrosion Junk	Rack at a Hydropower Station 11-30	Creep Failure of Admiralty Brass Tubes in
Science 3-34	MMO-Coated Titanium Anodes for	an After-Cooler 1-52
	Cathodic Protection—Part 1 5-26	m.11
Acrylic resin	MMO-Coated Titanium Anodes for	Bridge
Tanninsulfonic Acid-Doped Polyaniline for	Cathodic Protection—Part 2 6-24	Anode Selection for Protection of
Protection of Cold-Rolled Steel 2-38		Reinforced Concrete Structures 1-26
A 4-041-1-1	Anode, deep bed	Braminated anam.
Additive, non-skid	Check Solar Weather Before Performing	Brominated epoxy
Painting at Night in the Gulf of Mexico 2-31	Pipeline CP Evaluation 6-30	Properties of a New High-Tg FBE Coating
Admiralty brass	MMO-Coated Titanium Anodes for	for High-Temperature Service 4-36
Creep Failure of Admiralty Brass Tubes in	Cathodic Protection—Part 2 6-24	Bronze
an After-Cooler1-52		Corrosion of Old Whaling Station
all Alter-Cooler	Anode, mixed metal oxide	Processing Equipment in Antarctica 4-57
After-cooler	Anode Selection for Protection of	Frocessing Equipment in Antarctica 4-37
Creep Failure of Admiralty Brass Tubes in	Reinforced Concrete Structures 1-26	Building, steel-framed
an After-Cooler 1-52	MMO-Coated Titanium Anodes for	Anode Selection for Protection of
	Cathodic Protection—Part 1 5-26	Reinforced Concrete Structures 1-27
Agitation	MMO-Coated Titanium Anodes for	Treminorcea Concrete Citactares 1-27
Agitator Corrosion in Wet Phosphoric Acid	Cathodic Protection—Part 2 6-24	Carbon fiber
Production2-51		Anode Selection for Protection of
	Anode, probe	Reinforced Concrete Structures 1-27
Agitator, reactor	Anode Selection for Protection of	
Agitator Corrosion in Wet Phosphoric Acid	Reinforced Concrete Structures 1-27	Carbon steel
Production 2-50		A New Method for Pipeline Integrity
	Anode, ribbon	Management 1-42
Alloy	Anode Selection for Protection of	•
Corrosion of UNS N06625 Nozzles in a	Reinforced Concrete Structures 1-27	Cast iron
Biomass Fluidized Bed Boiler 9-74		Longevity of a Graphitized Cast Iron Water
	Anode, silicon iron	Main 5-30
Alloy, Inconel	Anode Selection for Protection of	
Case Histories: Stress Corrosion Cracking	Reinforced Concrete Structures 1-26	Cathodic disbondment
of Various Alloys—Part 2 9-71	Amelianica	Properties of a New High-Tg FBE Coating
	Appliqués	for High-Temperature Service 4-36
Alloy, steel	Appliqués for Corrosion Protection in a	0.1.11
Case Histories: Stress Corrosion Cracking	Tropical Environment 6-38	Cathodic protection
of Various Alloys—Part 2 9-69	Asphaltic coating	Anode Selection for Protection of
Aluminum	Analysis of Ductile Iron Corrosion Data	Reinforced Concrete Structures 1-26
		Cathodic Protection of a Shiplock Trash
Case Histories: Stress Corrosion Cracking	from Operating Mains 2-22	Rack at a Hydropower Station 11-30
of Various Alloys—Part 2 9-72	Austenitic stainless steel	Check Solar Weather Before Performing
Anaerobic slime	Chloride Stress Corrosion Cracking of UNS	Pipeline CP Evaluation 6-30
Lining Prevents Biogenic Sulfide Corrosion	S20910 Stainless Steel 1-58	Correcting CIPS for Stray and Telluric
In Wastewater Systems 5-36	OLOUTO Otaliness Oteel	Current Interference 10-24
III Wastewater Systems 5-30	Bacteria, sulfate-reducing	Corrosion Mitigation of USS Monitor
Annealing	Detecting and Monitoring Bacteria in	Artifacts 10-56
Sigma Phase Formation of Type 310	Seawater Injection Systems 11-52	Galvanic Corrosion Study of Tin-Silver
Stainless Steel in a Lime Kiln Burner	Effect of Biogenic Sulfide on Corrosion of	Solder and Copper 6-58
Nozzle	Mild Steel 6-48	Internal Stray Current Interference from an
1402216 5-37		
Anode	SRB-Assisted MIC of Fire Sprinkler	External Current Source 8-40
Anode Selection for Protection of	Piping 2-46	I Told You So
Reinforced Concrete Structures 1-26	Biogenic sulfide	Low-Alloy Steels for Reinforcing Rods in
Cathodic Protection of a Shiplock Trash	Effect of Biogenic Sulfide on Corrosion of	Concrete 5-50
	Mild Steel 6-48	Mitigation Techniques for AC-DC Cathodic
Rack at a Hydropower Station 11-30		Decoupling 12-30
Galvanic Corrosion Study of Tin-Silver	Lining Prevents Biogenic Sulfide Corrosion	MMO-Coated Titanium Anodes for Cathodi
Solder and Copper 6-58	in Wastewater Systems 5-36	Protection—Part 1 5-20
MMO-Coated Titanium Anodes for	Understanding Biogenic Sulfide	MMO-Coated Titanium Anodes for Cathodi
Cathodic Protection—Part 1 5-26	Corrosion 11-36	Protection—Part 2 6-24

Using Coupons and ER Soil Corrosion	Coating, delamination	Concrete, biogenic sulfide corrosion
Probes in Applying Pipeline CP	Literature Review: The Delamination of	Understanding Biogenic Sulfide
Criteria 4-26	Organic Coating 11-40	Corrosion 11-36
Cathodic protection, bridge deck	Coating, epoxy	Concrete, high resistivity
Anode Selection for Protection of	Lining Prevents Biogenic Sulfide Corrosion	Estimating Long-Term Concrete Electrical
Reinforced Concrete Structures 1-26	In Wastewater Systems 5-36 Painting at Night in the Gulf of Mexico 2-30	Resistivity9-36
Cathodic protection, pipeline	Properties of a New High-Tg FBE Coating	Concrete, prestressed
Internal Stray Current Interference from an External Current Source 8-40	for High-Temperature Service 4-36	Three Myths About Corrosion of Steel in Concrete
Using Coupons and ER Soil Corrosion	Coating, fusion-bonded epoxy	Using Inhibitors to Protect Steel
Probes in Applying Pipeline CP	Properties of a New High-Tg FBE Coating	Prestressing in High-Performance
Criteria 4-26	for High-Temperature Service 4-36	Grouts 3-40
Cavitation	Coating, high-humidity	Concrete, reinforced
Agitator Corrosion in Wet Phosphoric Acid	Painting at Night in the Gulf of Mexico 2-30	Anode Selection for Protection of
Production 2-51	Coating, high-temperature	Reinforced Concrete Structures 1-26
Change management	Properties of a New High-Tg FBE Coating	Corrosion in Reinforced Concrete Exposed
A New Method for Pipeline Integrity		to Chloride-Contaminated Waters 3-48
Management 1-44	for High-Temperature Service 4-36	Low-Alloy Steels for Reinforcing Rods in Concrete 5-56
	Coating, inspection	
Chloride	Managing a Coating & Plating Supply	MMO-Coated Titanium Anodes for
Corrosion in Reinforced Concrete Exposed	Chain 1-36	Cathodic Protection—Part 2 6-24 Performance of Concrete Bars on Industrial
to Chloride-Contaminated Waters 3-48	Cooting marine or constal	
Phlogiston and Modern Corrosion Junk	Coating, marine or coastal	Platform Substations
Science 3-32	Appliqués for Corrosion Protection in a Tropical Environment 6-38	Three Myths About Corrosion of Steel in Concrete 8-70
Close interval potential surveys	Coating, Monte Carlo model	Concrete, testing
Correcting CIPS for Stray and Telluric	Coating Assessment for Prediction of	Performance of Concrete Bars on Industrial
Current Interference 10-24	Service Life	Platform Substations 3-58
Coating	Coating, night application	Condenser
Coating Assessment for Prediction of		
Service Life 9-46	Painting at Night in the Gulf of Mexico 2-30	Creep Failure of Admiralty Brass Tubes in
How VOC and HAPS Regulations Affect	Coating, offshore	an After-Cooler 1-52
Coating Applications 12-36	Painting at Night in the Gulf of Mexico 2-30	Conductive-sprayed mortar
Managing a Coating & Plating Supply	t annual grant region in the dan or memor 2 or	Anode Selection for Protection of
Chain 1-36	Coating, pipeline	Reinforced Concrete Structures 1-27
Phlogiston and Modern Corrosion Junk	Properties of a New High-Tg FBE Coating	
Science 3-34	for High-Temperature Service 4-36	Contamination, lead
Castian and instinct	C4'	Lead Contamination of Condensed
Coating, application	Coating, process	Water 4-46
How VOC and HAPS Regulations Affect	Managing a Coating & Plating Supply	C
Coating Applications	Chain 1-36	Copper
MMO-Coated Titanium Anodes for Cathodic Protection—Part 1 5-26	Coatings, surface preparation	Failure Analysis: Microbiologically Influenced Corrosion in a Copper Tube
	Soda Blasting Surface Preparation for	Chiller 11-48
Coating, appliqués	Maintenance Painting 8-50	
Appliqués for Corrosion Protection in a	Compressibility factor	Copper tubular components
Tropical Environment 6-38	A New Method for Pipeline Integrity	Galvanic Corrosion Study of Tin-Silver Solder and Copper
Coating, asphaltic	Management 1-42	
Analysis of Ductile Iron Corrosion Data		Corrosion, biogenic sulfide
from Operating Mains 2-22	Concrete Estimating Long-Term Concrete Electrical	Effect of Biogenic Sulfide on Corrosion of Mild Steel6-48
Coating, concrete	Resistivity 9-36	Lining Prevents Biogenic Sulfide Corrosion
Lining Prevents Biogenic Sulfide Corrosion	Performance of Concrete Bars on Industrial	
In Wastewater Systems 5-36	Platform Substations	in Wastewater Systems 5-36 Understanding Biogenic Sulfide
Coating, conductive	Concrete 8-70	Corrosion 11-36
Anode Selection for Protection of	Julia eta 0-70	Corrosion control system
Reinforced Concrete Structures 1-26		I Told You So

Corrosion, engineering	Lead Contamination of Condensed	Cyclic acid regeneration
Offshore Assets: From Corrosion	Water 4-46	Phlogiston and Modern Corrosion Junk
Engineering to Corrosion	SRB-Assisted MIC of Fire Sprinkler	Science 3-32
Management 10-35	Piping 2-46	
Failure Analysis, Part 1—Theory and		Delamination
Engineering 12-54	Corrosion, pitting A New Method for Pipeline Integrity	Literature Review: The Delamination of Organic Coating 11-40
Corrosion fatigue	Management 1-43	
Agitator Corrosion in Wet Phosphoric Acid	Chloride Stress Corrosion Cracking of UNS	Ductile iron
Production2-51	S20910 Stainless Steel 1-58 Empirical Equations to Predict Conditions	Analysis of Ductile Iron Corrosion Data from Operating Mains 2-22
Corrosion inhibitor	for Solid Deposition 8-58	Case Histories: Stress Corrosion Cracking
Literature Review: The Delamination of Organic Coating 11-40	SRB-Assisted MIC of Fire Sprinkler	of Various Alloys—Part 2 9-67
Standards for Laboratory Evaluation of	Piping 2-47	Ductility
Oilfield Corrosion Inhibitors 5-46	Corrosion, stress corrosion cracking	Sigma Phase Formation of Type 310
Using Inhibitors to Protect Steel	Agitator Corrosion in Wet Phosphoric Acid	Stainless Steel in a Lime Kiln Burner
Prestressing in High-Performance	Production2-51	Nozzle 3-54
Grouts 3-40	Case Histories: Stress Corrosion Cracking	
Grouts 3-40	of Various Alloys—Part 1 8-74	Electrical Resistivity
Corrosion inhibitor, pipeline	Case Histories: Stress Corrosion Cracking	Estimating Long-Term Concrete Electrical
Standards for Laboratory Evaluation of	of Various Alloys—Part 2 9-67	Resistivity 9-36
Oilfield Corrosion Inhibitors 5-46		Electrocative conduction not were
	Chloride Stress Corrosion Cracking of UNS S20910 Stainless Steel 1-58	Electroactive conducting polymers Literature Review: The Delamination of
Corrosion inhibitor, standards		
Standards for Laboratory Evaluation of	Creep Failure of Admiralty Brass Tubes in an After-Cooler	Organic Coating 11-40
Oilfield Corrosion Inhibitors 5-46	an Arter-Cooler 1-52	Electrocatalytic coating
Compaign automal	Corrosion, sulfide	MMO-Coated Titanium Anodes for
Corrosion, external	Effect of Biogenic Sulfide on Corrosion of	Cathodic Protection—Part 1 5-27
Analysis of Ductile Iron Corrosion Data	Mild Steel 6-48	MMO-Coated Titanium Anodes for
from Operating Mains2-22 Corrosion, formicary	Lining Prevents Biogenic Sulfide Corrosion In Wastewater Systems5-36	Cathodic Protection—Part 2 6-24
Formicary Corrosion of Cupronickel	Understanding Biogenic Sulfide	Electrodes, mixed metal oxide
Tubing4-52	Corrosion 11-36	MMO-Coated Titanium Anodes for Cathodic Protection—Part 1 5-26
Corresion, galvanie	Corrosion, tuberculation	MMO-Coated Titanium Anodes for
Galvanic Corrosion Study of Tin-Silver	Case History: Tuberculation Corrosion in	Cathodic Protection—Part 2 6-24
Solder and Copper 6-58	Industrial Effluents 9-54	
образования образо		Encasement, polyethylene
Corrosion, internal	Corrosion, underdeposit	Analysis of Ductile Iron Corrosion Data
A New Method for Pipeline Integrity	Empirical Equations to Predict Conditions	from Operating Mains 2-22
Management 1-42	for Solid Deposition 8-58	Ероху
Corrosion, management	Coupon	Lining Prevents Biogenic Sulfide Corrosion
A New Method for Pipeline Integrity	Using Coupons and ER Soil Corrosion	in Wastewater Systems 5-36
Management 1-44	Probes in Applying Pipeline CP	Painting at Night in the Gulf of Mexico 2-30
Offshore Assets: From Corrosion	Criteria 4-26	Properties of a New High-Tg FBE Coating
Engineering to Corrosion		for High-Temperature Service 4-36
Management 10-36	Creep, elevated temperature	
	Creep Failure of Admiralty Brass Tubes in	Epoxy, brominated
Corrosion, measurement	an After-Cooler 1-53	Properties of a New High-Tg FBE Coating
Corrosion Measurements in an Historic	Curreniskel	for High-Temperature Service 4-36
Building 11-60	Cupronickel Formicary Corrosion of Cupronickel Tubing.	Francisco banded
Corrosion, microbiologically		Epoxy, fusion-bonded
influenced	4-52	Properties of a New High-Tg FBE Coating for High-Temperature Service 4-36
Case History: Tuberculation Corrosion in	Current, telluric	for riight-temperature Service 4-30
Industrial Effluents 9-54	Check Solar Weather Before Performing	Epoxy, high-temperature
Detecting and Monitoring Bacteria in	Pipeline CP Evaluation 6-30	Properties of a New High-Tg FBE Coating
	Correcting CIPS for Stray and Telluric	for High-Temperature Service 4-36
Seawater Injection Systems 11-52 Failure Analysis: Microbiologically	Current Interference	
Influenced Corrosion in a Copper Tube		Epoxy, weathering
		Properties of a New High-Tg FBE Coating
Chiller 11-48		for High-Temperature Service 4-36

Erosion	Freeze-thaw damage	High-temperature creep damage
Agitator Corrosion in Wet Phosphoric Acid Production2-51	Anode Selection for Protection of Reinforced Concrete Structures 1-26	Sigma Phase Formation of Type 310 Stainless Steel in a Lime Kiln Burner
		Nozzle 3-54
Erosion-corrosion	Fusion-bonded epoxy	
Agitator Corrosion in Wet Phosphoric Acid	Properties of a New High-Tg FBE Coating	Historic
Production 2-51	for High-Temperature Service 4-36	Corrosion Measurements in an Historic
Farmelt	P	Building11-60
External corrosion	Fusion-bonded epoxy,	Corrosion Mitigation of USS Monitor
Analysis of Ductile Iron Corrosion Data	high-temperature	Artifacts 10-56
from Operating Mains 2-22	Properties of a New High-Tg FBE Coating	
Failure analysis	for High-Temperature Service 4-36	Hydrogen sulfide
Chloride Stress Corrosion Cracking of UNS	Fusion-bonded epoxy, weathering	A New Method for Pipeline Integrity
S20910 Stainless Steel 1-58	Properties of a New High-Tg FBE Coating	Management 1-42
Creep Failure of Admiralty Brass Tubes in	for High-Temperature Service 4-36	Lining Prevents Biogenic Sulfide Corrosion
an After-Cooler	for riigii-temperature Service 4-30	In Wastewater Systems 5-36
an Arter-Cooler1-52	Galvanic corrosion	I!
Failure, prediction	Galvanic Corrosion Study of Tin-Silver	Impingement
A New Method for Pipeline Integrity	Solder and Copper 6-58	Agitator Corrosion in Wet Phosphoric Acid
Management 1-43		Production 2-51
· · · · · · · · · · · · · · · · · · ·	Galvanized piping	Inconel alloy
Feature Articles (Various Subjects)	SRB-Assisted MIC of Fire Sprinkler	Case Histories: Stress Corrosion Cracking
A Closer Look at Long-Term Nuclear Waste	Piping 2-46	of Various Alloys—Part 2 9-71
Disposal 9-28		or various Alloys—Part 2 3-71
Corrosion at Prudhoe Bay-A Lesson on	Gas, sour	Industrial Computerized Tomography
the Line 8-26	A New Method for Pipeline Integrity	Failure Analysis: Using Industrial
Galvanic Corrosion Threatens Historic	Management 1-42	Computerized Tomography for
Lighthouse 10-20	Can awant	Corrosion Investigation 12-60
New Training Facility Takes Root 5-24	Gas, sweet	
Red Cliff Arch Bridge: Spanning the Gap	A New Method for Pipeline Integrity	Inhibitor, corrosion
Between Historic Construction and	Management 1-42	Literature Review: The Delamination of
Modern Technology 9-32	Gasket selection	Organic Coating 11-40
Rust at Bay: Houston's Port Casts Off	Gasket Selection for Stainless Steels in	Standards for Laboratory Evaluation of
Corrosion 1-22	Seawater 10-50	Oilfield Corrosion Inhibitors 5-46
	Seawater 10-30	Using Inhibitors to Protect Steel
Rusting from the Inside Out—Unique Window Design Promotes Corrosion of	Grain growth	Prestressing in High-Performance
	Sigma Phase Formation of Type 310	Grouts 3-40
Historic San Francisco Building 11-26	Stainless Steel in a Lime Kiln Burner	
Trends in Testing: Present and Future 3-22	Nozzle 3-56	Integrity management system
Tulsa's Time Capsule Car Succumbs to		Offshore Assets—From Corrosion
Corrosion 8-36	Graphite	Engineering to Corrosion
University of Akron and Partners Lay	Anode Selection for Protection of	Management 10-34
Groundwork for New Degree	Reinforced Concrete Structures 1-27	
Program 4-24		Integrity, pipeline
Wanted: Corrosion Professionals 12-26	Graphitization	A New Method for Pipeline Integrity
Fire enrighter	Longevity of a Graphitized Cast Iron Water	Management 1-42
Fire sprinkler	Main 5-30	Internal corrosion
SRB-Assisted MIC of Fire Sprinkler	Grout	A New Method for Pipeline Integrity
Piping2-46		
Fluid velocity	Using Inhibitors to Protect Steel	Management 1-42
Corrosion of Low-Velocity, High Water Cut	Prestressing in High-Performance	Internal corrosion direct assessment
Oil Emulsion Pipelines 8-64	Grouts 3-40	A New Method for Pipeline Integrity
On Emulaion 1 ipennes	Heat exchanger	Management 1-42
Fluidized bed	Creep Failure of Admiralty Brass Tubes in	management
Corrosion of UNS N06625 Nozzles in a	an After-Cooler1-52	Internal stray current
Biomass Fluidized Bed Boiler 9-74	Failure Analysis: Erosion-Corrosion Failure	Internal Stray Current Interference from an
	of a Spiral Heat Exchanger 12-50	External Current Source 8-40
Formicary corrosion	or a opiral near exchanger 12-30	
Formicary Corrosion of Cupronickel	High-temperature coating	Ion migration
Tubing 4-52	Properties of a New High-Tg FBE Coating	Phlogiston and Modern Corrosion Junk
	for High-Temperature Service 4-36	Science 3-34

Iron	Management of change	Oil industry
Analysis of Ductile Iron Corrosion Data	A New Method for Pipeline Integrity	Effect of Biogenic Sulfide on Corrosion of
from Operating Mains 2-22	Management 1-44	Mild Steel 6-48
Case Histories: Stress Corrosion Cracking		Empirical Equations to Predict Conditions
of Various Alloys-Part 2 9-67	Management, pipeline integrity	for Solid Deposition 8-58
Corrosion Measurements in an Historic	A New Method for Pipeline Integrity	
Building 11-60	Management 1-42	Oxidation
Corrosion Mitigation of USS Monitor	Marine structure, jetty	MMO-Coated Titanium Anodes for
Artifacts 10-56	Anode Selection for Protection of	Cathodic Protection—Part 1 5-26
Longevity of a Graphitized Cast Iron Water	Reinforced Concrete Structures 1-27	MMO-Coated Titanium Anodes for
Main 5-30	Heimorcea Concrete Structures 1-27	Cathodic Protection—Part 2 6-24
Phlogiston and Modern Corrosion Junk	Microbiologically influenced	Paper industry
Science 3-32	corrosion	Sigma Phase Formation of Type 310
	Case History: Tuberculation Corrosion in	Stainless Steel in a Lime Kiln Burner
Iron, cast	Industrial Effluents 9-54	Nozzle
Longevity of a Graphitized Cast Iron Water	Detecting and Monitoring Bacteria in	1102210
Main 5-30	Seawater Injection Systems 11-52	Phosphoric acid
Iron, ductile	Failure Analysis: Microbiologically	Agitator Corrosion in Wet Phosphoric Acid
Analysis of Ductile Iron Corrosion Data	Influenced Corrosion in a Copper Tube	Production 2-50
from Operating Mains2-22	Chiller 11-48	
Case Histories: Stress Corrosion Cracking	Lead Contamination of Condensed	Phreatic mantle
of Various Alloys—Part 2	Water 4-46	Corrosion in Reinforced Concrete Exposed
or various Alloys—Part 2 3-07	SRB-Assisted MIC of Fire Sprinkler	to Chloride-Contaminated Waters 3-48
Kiln, lime	Piping2-46	Pipeline
Sigma Phase Formation of Type 310		A Systematic Approach to Prevent Internal
Stainless Steel in a Lime Kiln Burner	Mild steel corrosion	Corrosion of Pipelines
Nozzle 3-54	Effect of Biogenic Sulfide on Corrosion of	Pipeline Ultrasonic Intelligent Inspection
	Mild Steel 6-48	Device and Assessment Software 9-62
Lavoisier	Mitigation	Device and Assessment Software 5-02
Phlogiston and Modern Corrosion Junk	A New Method for Pipeline Integrity	Pipeline, cathodic protection
Science 3-32	Management 1-42	Internal Stray Current Interference from an
Lead, in water	Wallagement	External Current Source 8-40
Lead Contamination of Condensed	Mixed metal oxide-coated	Using Coupons and ER Soil Corrosion
Water 4-46	MMO-Coated Titanium Anodes for	Probes in Applying Pipeline CP
vvate: 4-40	Cathodic Protection—Part 1 5-26	Criteria 4-26
Lead wire insulation	MMO-Coated Titanium Anodes for	
MMO-Coated Titanium Anodes for	Cathodic Protection—Part 2 6-24	Pipeline, coating
Cathodic Protection—Part 1 5-28		Properties of a New High-Tg FBE Coating
	Modeling, pipeline integrity	for High-Temperature Service 4-36
Legionella	A New Method for Pipeline Integrity	Pipeline corrosion inhibitor
SRB-Assisted MIC of Fire Sprinkler	Management 1-42	Calcium Carbonate Precipitation in the
Piping 2-48	Monitoring, pipeline integrity	Presence of Inhibitors 10-42
Lime kiln	A New Method for Pipeline Integrity	
Sigma Phase Formation of Type 310	Management 1-42	Standards for Laboratory Evaluation of Oilfield Corrosion Inhibitors 5-46
Stainless Steel in a Lime Kiln Burner	Wanagement 1-42	Officed Corrosion Inhibitors 5-40
Nozzle	Mortar, conductive sprayed	Pipeline integrity
1402216 3-34	Anode Selection for Protection of	A New Method for Pipeline Integrity
Lining	Reinforced Concrete Structures 1-27	Management 1-42
Lining Prevents Biogenic Sulfide Corrosion		
In Wastewater Systems 5-36	Offshore	Pipeline, interior corrosion
	Offshore Assets: From Corrosion	Internal Stray Current Interference from an
Maintenance, pipeline	Engineering to Corrosion	External Current Source 8-40
A New Method for Pipeline Integrity	Management 10-34	Disaline internal servenies
Management 1-42	Painting at Night in the Gulf of	Pipeline, internal corrosion
Management, integrity	Mexico 2-30	A New Method for Pipeline Integrity
Offshore Assets: From Corrosion	Oilfield	Management
Engineering to Corrosion	Standards for Laboratory Evaluation of	A Systematic Approach to Prevent Internal
	The state of the s	Corrosion of Pipelines 12-44
Management 10-34	Oilfield Corrosion Inhibitors 5-46	Calcium Carbonate Precipitation in the
		Presence of Inhibitors 10-42

Correction of Law Valority High Water Cut	Decks sell	C-11
Corrosion of Low-Velocity, High Water Cut Oil Emulsion Pipelines8-64	Probe, soil Using Coupons and ER Soil Corrosion	Soil corrosion probe Using Coupons and ER Soil Corrosion
on amaion i pomoo minimi o o i	Probes in Applying Pipeline CP	Probes in Applying Pipeline CP
Pipeline, natural gas	Criteria 4-26	Criteria 4-26
Check Solar Weather Before Performing		_
Pipeline CP Evaluation 6-30	Process cooling systems	Soil evaluation
Pipeline Ultrasonic Intelligent Inspection	Galvanic Corrosion Study of Tin-Silver	Analysis of Ductile Iron Corrosion Data
Device and Assessment Software 9-62	Solder and Copper 6-58	from Operating Mains2-22
Pipeline, solid deposition	Reactor agitator	Solar activity
Empirical Equations to Predict Conditions	Agitator Corrosion in Wet Phosphoric Acid	Check Solar Weather Before Performing
for Solid Deposition 8-58	Production2-50	Pipeline CP Evaluation 6-30
Pipeline, tuberculation	Reference electrode, embedded	Solder, tin-silver (SnAg)
Case History: Tuberculation Corrosion in	Anode Selection for Protection of	Galvanic Corrosion Study of Tin-Silver
Industrial Effluents 9-54	Reinforced Concrete Structures 1-26	Solder and Copper 6-58
Pipeline, ultrasonic inspection	Reference electrode, submersible	Sour gas
Pipeline Ultrasonic Intelligent Inspection	Submersible Reference Electrodes	A New Method for Pipeline Integrity
Device and Assessment Software 9-62	Revisited 10-30	Management 1-42
		Chloride Stress Corrosion Cracking of UNS
Piping, galvanized	Reinforced concrete	S20910 Stainless Steel 1-58
SRB-Assisted MIC of Fire Sprinkler	Anode Selection for Protection of	
Piping 2-46	Reinforced Concrete Structures 1-26	Sprinkler, fire
Pitting	Corrosion in Reinforced Concrete Exposed	SRB-Assisted MIC of Fire Sprinkler
A New Method for Pipeline Integrity	to Chloride-Contaminated Waters 3-48 Low-Alloy Steels for Reinforcing Rods in	Piping 2-46
Management 1-43	Concrete 5-56	Stainless steel
Chloride Stress Corrosion Cracking of UNS	MMO-Coated Titanium Anodes for	Case Histories: Stress Corrosion Cracking
S20910 Stainless Steel 1-58	Cathodic Protection—Part 2 6-24	of Various Alloys-Part 1 8-74
Empirical Equations to Predict Conditions	Performance of Concrete Bars on Industrial	Chloride Stress Corrosion Cracking of UNS
for Solid Deposition 8-58	Platform Substations 3-58	S20910 Stainless Steel 1-58
SRB-Assisted MIC of Fire Sprinkler	Three Myths About Corrosion of Steel in	Corrosion of UNS N06625 Nozzles in a
Piping 2-47	Concrete 8-70	Biomass Fluidized Bed Boiler 9-74
Plating		Gasket Selection for Stainless Steels in
Managing a Coating & Plating Supply	Resin, acrylic	Seawater 10-50
Chain1-36	Tanninsulfonic Acid-Doped Polyaniline for Protection of Cold-Rolled Steel 2-38	Sigma Phase Formation of Type 310 Stainless Steel in a Lime Kiln Burner
	Protection of Cold-Rolled Steel 2-38	Nozzle
Polyaniline	Salt	NOZZIE 3-34
Tanninsulfonic Acid-Doped Polyaniline for	Phlogiston and Modern Corrosion Junk	Stainless steel, austenitic
Protection of Cold-Rolled Steel 2-38	Science 3-32	Chloride Stress Corrosion Cracking of UNS
Polyethylene encasement	0 1 1 1	S20910 Stainless Steel 1-58
Analysis of Ductile Iron Corrosion Data	Scale deposits Calcium Carbonate Precipitation in the	Steel
from Operating Mains 2-22	Presence of Inhibitors 10-42	Corrosion of Old Whaling Station
	Presence of Illimbitors 10-42	Processing Equipment in
Polymer, conductive	Seawater	Antarctica4-57
Literature Review: The Delamination of	Detecting and Monitoring Bacteria in	
Organic Coating	Seawater Injection Systems 11-52	Steel, alloy
Protection of Cold-Rolled Steel 2-38	Gasket Selection for Stainless Steels in	Case Histories: Stress Corrosion Cracking
Protection of Cold-Holled Steel 2-30	Seawater 10-50	of Various Alloys—Part 2 9-69
Precipitation, calcium carbonate	Sigma phase embrittlement	Gasket Selection for Stainless Steels in
Calcium Carbonate Precipitation in the	Sigma Phase Formation of Type 310	Seawater 10-50
Presence of Inhibitors 10-42	Stainless Steel in a Lime Kiln Burner	Steel, austenitic
Prestressed concrete	Nozzle 3-54	Sigma Phase Formation of Type 310
Three Myths About Corrosion of Steel	Code blooding	Stainless Steel in a Lime Kiln Burner
in Concrete 8-70	Soda blasting	Nozzle 3-54
Using Inhibitors to Protect Steel	Soda Blasting Surface Preparation for	Steel, carbon
Prestressing in High-Performance	Maintenance Painting 8-50	A New Method for Pipeline Integrity
Grouts 3-40		Management 1-42

Steel, frame Anode Selection for Protection of Sulfide corrosion Effect of Biogenic Sulfide on Corrosion of MMO-Coated Titanium	Anodes for
	—Part 2 6-24
Lining Prevents Biogenic Sulfide Corrosion	
Steel, in concrete in Wastewater Systems	
Low-Alloy Steels for Reinforcing Rods in Understanding Biogenic Sulfide Agitator Corrosion in V	
Concrete	2-51
Three Myths About Corrosion of Steel in	
Concrete	625 Nozzles in a
Osing inhibitors to Protect Steel lanninsulfonic Acid-Doped Polyannine for	Bed Boiler 9-74
C	
Supply chain	
Steel, low alloy Managing a Coating & Plating Supply A New Method for Pipe	
Low-Ailby Steels for heimorching hous in Chairmann 1-30	1-42
Concrete	
Steel, plate Soda Blasting Surface Preparation for Analysis of Ductile Iron	n Corrosion Data
Tanninsulfonic Acid-Doped Polyaniline for Maintenance Painting8-50 from Operating Mai	ins 2-22
Protection of Cold-Rolled Steel 2-38 Case History: Tubercul	lation Corrosion in
Sweet gas Industrial Effluents	9-54
Steel, stainless A New Method for Pipeline Integrity Lining Prevents Bioger	
	tems 5-36
of Various Alloys—Part 1	
Chloride Stress Corrosion Cracking or Chis	11-36
S20910 Stainless Steel 1-58 Corrosion of UNS N06625 Nozzles in a Protection of Cold-Rolled Steel 2-38 Water	
Analysis of Ductile Iron	n Corrosion Data
Cooket Selection for Steinless Steels in	nins 2-22
Calcium Carbonate Pro	ecipitation in the
Sigma Phase Formation of Type 310 Protection of Cold-Rolled Steel 2-38 Presence of Inhibit	tors 10-42
Stainless Steel in a Lime Kiln Burner Tank bottom Cathodic Protection of	
	wer Station 11-30
Cathodic Protection—Part 2 6-25 Lead Contamination of	
·	4-46
Correcting CIPS for Stray and Telluric Telluric current interference Current Interference Tourism CIPS for Stray and Telluric Water cooling	
Cross Esilves of Admir	ralty Brass Tubes in
Estimating Long-Term Concrete Lieutrical Current interference	1-52
Internal Stray Current Interference from an Thermal-sprayed zinc	
External Current Source 9 40 Anode Selection for Protection of Water-jetting	0 11 -1114 - 1 - 0 04
Reinforced Concrete Structures 1-27 Painting at Night in the	e Gulf of Mexico 2-31
Stress corrosion cracking Tip cilver (SpAg) colder Water utility	
Agitator Corrosion in Wet Phosphoric Acid	Concrete Electrical
Production Resistivity	9-36
Told You So	3-26
of Various Alloys—Part 1 8-74 Case Histories: Stress Corrosion Cracking MMO Coated Titanium Anados for Welding	
William All Date College Hamilian Anodes for	on of Tuno 210
Chlorida Street Coursian Conding of LINE	
COOM Chairles Charles Charles 4 50	3-56
Creep Failure of Admiralty Brass Tubes in	
an After-Cooler	
Creep Failure of Admiralty Brass Tubes in MMO-Coated Titaniur	
Sulfate-reducing bacteria an After-Cooler	on—Part 2 6-24
Detecting and Monitoring Bacteria in Failure Analysis: Microbiologically	ved
I dilute Alialysis, wilciobiologically	
Seawater Injection Systems 11-52 Influenced Corrosion in a Copper Tube	Totection of
Seawater Injection Systems 11-52 Effect of Biogenic Sulfide on Corrosion of Chiller	ete Structures 1-27
Seawater Injection Systems	
Seawater Injection Systems 11-52 Effect of Biogenic Sulfide on Corrosion of Chiller	

Author Index

Almeraya Calderón, F., 11-60 Amjad, Z., 10-42 Anderson, E., 9-36 Ansuini, F., 4-56 Arcury, D., 6-58 Ault, J.P., 9-46

Babakr, A.M., 9-54
Bartos, M., 5-46
Berry, B.C., 2-38
Bin, X., 12-60
Bjegovic, D., 3-40
Borunda, T.A., 11-60
Broomfield, J., 1-26
Brossia, C.S., 10-56
Burke, D., 9-36
Byrne, G., 10-50

Chandra, K., 1-42 Cochran, S., 9-36 Cole, C.V., 2-38 Corbett, R., 4-52, 5-56

Davis, G.D., 6-38 De Rincon, O.T., 3-48 Deason, D., 6-38 Decker, O.W., 4-36 Delgado, S., 3-48 Doiron, A., 1-42, 8-58

Ellor, J.A., 9-46 Ernes, L.M., 5-26, 6-24

Farinha, P.A., 2-46 Fernance, N., 2-46 Fitzgerald, J.H., 3-26, 5-30 Fouche, P., 12-78 Francis, R., 10-50 Frumuselu, D., 3-58

Gaona Tiburcio, C., 11-60 García-Villalobos, J.L., 11-52 Giurconiu, C., 3-58 Golestanipour, M., 1-58 Gonclaves, P., 10-56 Greenwood, C., 4-24

Hausmann, D.A., 8-70 Holtsbaum, W.B., 8-40 Howard, W., 1-36 Jacobson, G.A., 8-26, 8-36 Javaherdashti, R., 2-46 Jeffers, T.E., 4-36 Johnson, S.R., 6-30 Judice, Jr., K., 2-30

Kain, V., 1-42 Khan, N.A., 4-26 Kirk, M., 12-36 Kish, J.R., 9-74 Kramer, J., 9-32 Kroon, D.H., 5-26, 6-24 Krop, D., 10-56

Larsen, K.R., 9-28, 10-20, 11-26, 12-26 Le Borgne, S., 11-52 LeCompte, J., 8-50

Martinez Villafañe, A., 11-60 McDonald, M.F., 8-64 Mitman, R., 1-23, 3-23, 5-24 Mohapatra, S., 6-58 Morshed, A., 10-34 Mostofi, J., 1-58

Nelson, L., 9-36 Neri Segura, F.J., 11-60 Nicholson, P., 10-24 Nordgren, E., 10-56 Numedahl, G., 12-30

O'Dea, V., 5-36, 11-36 Olszewski, A., 4-46, 4-52, 5-56, 11-48

Paller, J., 4-46
Panneerselvam, T., 5-46
Papavinasam, S., 1-42, 5-46, 8-58
Park, R.M., 10-30
Peiwen, Q., 9-62
Perdomo, J.J., 3-54
Pham, L., 9-36
Pimenta, G., 12-50

Qi, Z., 9-62

Reda, M., 11-40 Reitz, W., 12-54 Revie, R.W., 1-42, 5-46, 8-58 Rizk, T.Y., 6-48 Romero, J.M., 11-52 Sánchez, E., 3-48 Sánchez, M.A., 3-48 Santillan, N., 2-50 Schilling, M.S., 3-32 Schindelholz, E., 10-56 Schorr, M., 2-50 Seguin, R., 9-74 Serdar, M., 3-40 Shafiee, B., 1-42 Shaohua, X., 12-60 Sharma, B.P., 1-42 Shengtao, Z., 12-60 Singbeil, D.L., 9-74 Spry, T.D., 3-54 Stipanovic, I., 3-40 Suess, S.J., 8-74, 9-67 Szeliga, M.J., 2-22

Tata, L.N.M., 12-44 Taylor, K.K., 2-38 Tianlu, C., 9-62 Tingting, H., 12-60 Tinnea, J., 9-36 Tinnea, R., 9-36

Valdez, B., 2-50 Vargo, T., 6-38 Videla, H.A., 11-52 Viswanathan, T., 2-38

Wang, M., 6-58

Xi-Chang, Z., 11-30

Yan, G., 11-30 Yan, L., 11-30 Yunovich, M., 10-56

Zhou, W., 4-36 Zlatev, R., 2-50 Zuhl, R.W., 10-42